


Assembly Instructions





HB-MOR50-4




Notes:

- 1. Please read this assembly instruction carefully before assembling the product
- 2. Check the quantity of all parts before assembling the product
- 3. Cut surfaces might be sharp, do not touch the cut surfaces of the tubes
- 4. Clean the product with a dry cloth if needed
- 5. Keep the product away from sulfuric acid, and hot or burning sources; do not expose the product directly to sunlight


Hardware Provided

| | | | | | |
|----------|---|--------|----------|---|-------|
| a |  | 24 PCS | b |  | 2 PCS |
| c |  | 2 PCS | |  | 1 PC |


Parts Identification



A
2PCS




B
4PCS




C
12PCS


Step 1



Step 2



Step 3



Step 4

