



When screwing the bolts in, do not tighten all the way until all 8 bolts are aprox 80% tight . Then proceed to fully tighten all 8 bolts.

