


## Exploded Drawing for Assembly



### Parts List

- A. Handles (2)
- B. Support Tubes (2)
- C. Connection Frames (2)
- D. Support Bars (2)
- E. Axle (1)
- F. PU Wheels (4)
- G. Board (1)

### Hardware List

- a. M8 x 80 Bolts (4)
- b. M8 x 65 Bolts (2)
- c. M8 x 60 Bolts (4)
- d. M8 x 35 Bolts (2)
- e. M8 Nylon Nuts (12)
- f. M8 Flat Washers (12)
- g. M12 Flat Washers (2)
- h. Cotter Pins (2)
- i. Castors (2)